

Lead & Copper Rule Revisions


Service Line Inventory Program

Update April 2026


We Need Your Help — and We Are Here to Make It Easy

You are receiving this letter because we have been unable to confirm the material of the water service line that connects your home, business, or premises to the water system. We would like to send a Weir River Water System representative to your location and identify the pipe material for you — at no charge. All we need you to do is complete an online form to get that process started.

To schedule your free appointment, please visit our website (www.weirriverwater.org) and complete the Service Line Assistance Form:



Once we receive your form, we will contact you within two weeks to schedule a convenient time.



Your Water Is Safe

The Weir River Water System is in full compliance with all current Lead and Copper Rule requirements. Our continued sampling confirms that our water is well below action levels for lead, and our current treatment process and maintenance programs are providing all customers with safe drinking water.

Why We Are Reaching Out

In 2021, the EPA revised the Lead and Copper Rule to require water systems to identify the material of every customer's service line. Beginning in 2024, it became our responsibility to document those materials for each home, business, and premises we serve. We submitted our initial inventory ahead of the October 16, 2024, deadline and will continue working toward a complete baseline inventory due November 1, 2027. For additional information and updates on the program please visit our dedication web page at [Lead Service Line Identification](#)

Here is a summary of what we found across our 12,727 service connections:

Description	Private Side / Town Side	Number of Services	% of System
Non Lead or Galvanized	Private Side & Town Side	8,655	68%
Galvanized - Identified	Private Side & Town Side	78	0.6%
Lead – Identified	Private Side & Town Side	7	0.05%
Unidentified	Private Side	3999	31%
Unidentified	Town Side	928	7%

Your service line falls into the unidentified category, which is why we are asking for your help. We have a dedicated Lead Service Line Identification page on our website with full information about this program and what you can expect.

[Lead Service Line Identification](#)

Again, completing the Service Line Assistance Form at weirriverwater.org is all it takes. We'll handle the rest. Thank you in advance for your time and attention to this important program.